


~ Ornament Lighting ~

by Zuda Gay Pease



Here are the two loops about 1" apart.



Supplies

Glass Ornament
Clay Sheet - Cane Sheet or Other Design
Wire - Strong Craft Wire
String of Mini Tree Lights
Translucent Liquid Sculpey (TLS)
Ribbon
Additional Cane Slices or Clay
Super Glue



4. Wrap the looped wire around something about the size of the top of the ornament.



5. Cover your glass ornament with clay.



1. Cut a wire about 7" long, I use a paintbrush handle to make loops in the wire.
2. Twist the wire a couple of times to make the first loop.

3. Twist a second loop.



You need to leave about 1" between the completed loops.



~ Ornament Lighting ~

by Zuda Gay Pease

This one is covered with a translucent flower veneer.



10. Bake to cure and finish as desired.

11. To hang the finished ornament, place a mini light into opening.



6. 11 Carefully fold the clay over the lip of the ornament's opening,

7. Roll it smooth. Be sure to cover sharp glass edge.

8. After the ornament is baked, and

sanded (if needed), super glue the wire around the top of the ornament to hold it in place.

12. Thread a ribbon through the wire loops.



9. Smear a bit of TLS to the wire and add leaf canes or a clay rope to cover the wire



13. Tie the ornament to a branch, turn on the lights and enjoy the glow.

